

VEID17.2 - BND200	S23RF	1024	Absolute pressure sensor, intake manifold, possibility: intake manifold pressure too high	During the shut-down phase the diagnostic function monitors the DME to determine whether the ambient air, intake manifold and boost pressure sensors are measuring the same pressure	P1245	Manifold Absolute Pressure Sensor X	Manifold Absolute Pressure Sensor	Afterrunning	The intake manifold pressure sensor deviates from the average for the pressure sensors (barometric pressure, boost pressure, intake manifold pressure) by more than 70 mbar	Potential problem scenario(s): - Defective wiring harness - Sensor has been tampered with - Sensor defective	This fault is logged in the control module's fault memory immediately	none	none	5 sec. after engine off	NO	none	Y	- Defective wiring harness - Sensor has been tampered with - Sensor defective	- Check wiring harness at sensor - Replace sensor	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	none	Possible apparent symptoms Best case scenario: None	Breakdown notice - none	none
VEID17.2 - BND200	S23RF	1025	Absolute pressure sensor, intake manifold, possibility: intake manifold pressure too low	The diagnostic function monitors the DME's barometric pressure sensor	P1229	Manifold Absolute Pressure Top Low	Manifold Absolute Pressure Sensor	Pressure	The fault is recognized when the voltage of the barometric pressure sensor + 0.5 V Potential problem scenario(s): - Internal DME fault, because barometric pressure sensor is located in the DME ECU - Sensor voltage above threshold	This fault is logged in the control module's fault memory immediately	none	none	5 sec. after engine off	NO	none	Y	- Internal DME fault, because barometric pressure sensor is located in the DME ECU - Sensor voltage above threshold	- Check an induction system (headlights, etc.) - Check an induction fault between turbocharger and intake air plenum - Check wiring harness between DME and boost pressure sensor - Replace DME	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	none	Possible apparent symptoms Best case scenario: None	Breakdown notice - none	none	
VEID17.2 - BND200	S23RF	1026	Absolute pressure sensor, intake manifold, possibility: intake manifold pressure too high	The diagnostic function monitors the DME's barometric pressure sensor	P1244	Manifold Absolute Pressure Sensor X	Manifold Absolute Pressure Sensor	Afterrunning	The fault is recognized when the voltage of the barometric pressure sensor + 0.5 V Potential problem scenario(s): - Internal DME fault, because barometric pressure sensor is located in the DME ECU - Sensor voltage above threshold	This fault is logged in the control module's fault memory immediately	none	none	5 sec. after engine off	NO	none	Y	- Internal DME fault, because barometric pressure sensor is located in the DME ECU - Sensor voltage above threshold	- Check an induction system (headlights, etc.) - Check an induction fault between turbocharger and intake air plenum - Check wiring harness between DME and boost pressure sensor - Replace DME	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	none	Possible apparent symptoms Best case scenario: None	Breakdown notice - none	none	
VEID17.2 - BND200	S23LA	1006	Absolute pressure sensor, intake pipe, electrical short circuit to GND	The diagnostic function monitors the intake manifold pressure sensor's upper voltage limit	P1208	Manifold Absolute Pressure/Barometric Pressure Sensor Circuit High	Manifold Absolute Pressure Sensor	Electrical	The voltage of the intake manifold pressure sensor exceeds 4.0 V Potential problem scenario(s): - Defect in wiring harness between DME and intake manifold pressure sensor - Intake manifold pressure sensor defective - Defective DME	This fault is logged in the control module's fault memory immediately	Terminal 15	none	none	none	NO	none	Y	- Defect in wiring harness between DME and intake manifold pressure sensor - Intake manifold pressure sensor defective - Defective DME	- Check wiring harness between intake manifold pressure sensor and DME - Replace intake manifold pressure sensor - Replace DME	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	none	Possible apparent symptoms Engine rpm roughly	Breakdown notice None	None
VEID17.2 - BND200	S23LA	1006	Absolute pressure sensor, intake pipe, electrical short circuit to GND	The diagnostic function monitors the intake manifold pressure sensor's upper voltage limit	P1208	Manifold Absolute Pressure Sensor Circuit High (Bank 1)	Manifold Absolute Pressure Sensor	Electrical	The voltage of the intake manifold pressure sensor exceeds 4.0 V Potential problem scenario(s): - Defect in wiring harness between DME and intake manifold pressure sensor - Intake manifold pressure sensor defective - Defective DME	This fault is logged in the control module's fault memory immediately	Terminal 15	none	none	none	NO	none	Y	- Defect in wiring harness between DME and intake manifold pressure sensor - Intake manifold pressure sensor defective - Defective DME	- Check wiring harness between intake manifold pressure sensor and DME - Replace intake manifold pressure sensor - Replace DME	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	none	Possible apparent symptoms Engine rpm roughly	Breakdown notice None	None
VEID17.2 - BND200	S23LB	1007	Absolute pressure sensor, intake pipe, electrical short circuit to earth	The diagnostic function monitors the intake manifold pressure sensor's lower voltage limit	P1207	Manifold Absolute Pressure/Barometric Pressure Sensor Circuit Low	Manifold Absolute Pressure Sensor	Electrical	The voltage of the intake manifold pressure sensor is less than 0.2 V Potential problem scenario(s): - Defect in wiring harness between DME and intake manifold pressure sensor - Intake manifold pressure sensor defective - Defective DME	This fault is logged in the control module's fault memory immediately	Terminal 15	none	none	none	NO	none	Y	- Defect in wiring harness between DME and intake manifold pressure sensor - Intake manifold pressure sensor defective - Defective DME	- Check wiring harness between intake manifold pressure sensor and DME - Replace intake manifold pressure sensor - Replace DME	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	none	Possible apparent symptoms Engine rpm roughly	Breakdown notice None	None
VEID17.2 - BND200	S23LB	1007	Absolute pressure sensor, intake pipe, electrical short circuit to earth	The diagnostic function monitors the intake manifold pressure sensor's lower voltage limit	P1207	Manifold Absolute Pressure Sensor Circuit Low (Bank 1)	Manifold Absolute Pressure Sensor	Electrical	The voltage of the intake manifold pressure sensor is less than 0.2 V Potential problem scenario(s): - Defect in wiring harness between DME and intake manifold pressure sensor - Intake manifold pressure sensor defective - Defective DME	This fault is logged in the control module's fault memory immediately	Terminal 15	none	none	none	NO	none	Y	- Defect in wiring harness between DME and intake manifold pressure sensor - Intake manifold pressure sensor defective - Defective DME	- Check wiring harness between intake manifold pressure sensor and DME - Replace intake manifold pressure sensor - Replace DME	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	none	Possible apparent symptoms Engine rpm roughly	Breakdown notice None	None
VEID17.2 - BND200	S23KC	1009	Ambient pressure sensor, electrical short or open circuit	The diagnostic function monitors the DME's barometric pressure sensor	P1229	Barometric Pressure Sensor X Circuit High	Ambient Pressure Sensor	Electrical	The fault is recognized when the barometric pressure sensor's signal voltage falls below 4.0 V Potential problem scenario(s): - DME defective	This fault is logged in the control module's fault memory immediately	Terminal 15	none	none	none	NO	U	Y	- DME defective	- Clear the ECU fault memory if the diagnostic fault code is logged again, replace the DME	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	none	Possible apparent symptoms ML on, customer proceeds to service facility	Breakdown notice None	None
VEID17.2 - BND200	S23KD	1001	Ambient pressure sensor, electrical short circuit to earth	The diagnostic function monitors the DME's barometric pressure sensor	P1228	Barometric Pressure Sensor X Circuit Low	Ambient Pressure Sensor	Electrical	The fault is detected by the internal calibration algorithm Potential problem scenario(s): - DME defective	This fault is logged in the control module's fault memory immediately	Terminal 15	none	none	none	NO	U	Y	- DME defective	- If the diagnostic fault code has been logged more than 3 times replace the DME	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	none	Possible apparent symptoms ML on, customer proceeds to service facility	Breakdown notice None	None
VEID17.2 - BND200	S23LA	1005	Ambient pressure sensor, overvoltage: Pressure too high	During the control module's shut-down phase the diagnostic function monitors the barometric pressure sensor, intake manifold pressure sensor and boost pressure sensor to determine whether they are all measuring the same pressure	P1238	Ambient Pressure Sensor Afterrunning Diagnosis Pressure Too High	Ambient Pressure Sensor	Afterrunning	The fault is recognized when the barometric pressure sensor deviates from the average for the pressure sensors (barometric pressure, boost pressure, intake manifold pressure) by more than 70 mbar Potential problem scenario(s): - Error in sensor - Sensor has been tampered with - Sensor defective	This fault is logged in the control module's fault memory immediately	none	none	5 sec. after engine off	NO	none	Y	- Error in sensor measurement - Sensor defective	- If the diagnostic fault code has been logged more than 3 times replace the DME	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	none	Possible apparent symptoms None	Breakdown notice - none	None	
VEID17.2 - BND200	S23LA	1005	Ambient pressure sensor, overvoltage: Pressure too low	The diagnostic function monitors the voltage of the boost pressure sensor	P1239	Ambient Pressure Sensor Afterrunning Diagnosis Pressure Too Low	Ambient Pressure Sensor	Afterrunning	The fault is recognized when the boost pressure sensor's voltage is + 0.2 V Potential problem scenario(s): - Defect in wiring harness between DME and boost pressure sensor - Boost pressure sensor defective - Defective DME	This fault is logged in the control module's fault memory immediately	none	none	5 sec. after engine off	NO	none	Y	- Defect in wiring harness between DME and boost pressure sensor - Boost pressure sensor defective - Defective DME	- Replace the DME if the fault code is currently present or has been logged more than three times	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	none	Possible apparent symptoms None	Breakdown notice - none	None	
VEID17.2 - BND200	S23AC	1016	Ambient pressure sensor, plausibility: Pressure too high	The diagnostic function monitors the barometric pressure sensor	P1238	Barometric Pressure Too High	Ambient Pressure	General	The fault is recognized when the barometric pressure sensor (P1238, P1239) barometric pressure sensor installed in DME ECU sensor voltage above threshold - DME defective wiring to sensor	This fault is logged in the control module's fault memory immediately	Terminal 15	none	none	none	NO	none	Y	- Barometric pressure sensor installed in DME ECU sensor voltage above threshold - DME defective wiring to sensor	- Replace the DME if the fault code is currently present or has been logged more than three times	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	none	Possible apparent symptoms None	Breakdown notice - none	A terminal status switch must be conducted before the fault can be cleared
VEID17.2 - BND200	S23AD	1017	Ambient pressure sensor, plausibility: Pressure too low	The diagnostic function monitors the barometric pressure sensor	P1239	Barometric Pressure Too Low	Ambient Pressure	General	The fault is recognized when a threshold is present Potential problem scenario(s): - Defective wiring harness - Short circuit to earth - Defective DME	This fault is logged in the control module's fault memory immediately	Terminal 15	none	none	none	NO	none	Y	- Defective wiring harness - Short circuit to earth - Defective DME	- Check wiring harness between electric coil and DME - Check coil relay when Terminal 15 is off - Check if it should be present at both sensor connectors (SC). When activated the relay should click loudly, while actually no resistance (it should be measured between the sensor connectors) - Defective wiring harness - Check relay for electric fan defective - Replace coil relay	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	none	Possible apparent symptoms None	Breakdown notice - none	A terminal status switch must be conducted before the fault can be cleared
VEID17.2 - BND200	S23AE	1018	Ambient pressure sensor, plausibility: Pressure irregularities	The diagnostic function monitors the plausibility of the barometric pressure relative to that measured in the previous driving cycle	P1247	Barometric Pressure Plausibility	Ambient Pressure	Plausibility	The fault is recognized in response to excessive variations in the value Potential problem scenario(s): - DME defective	This fault is logged in the control module's fault memory immediately	Terminal 15	none	none	none	NO	none	Y	- DME defective	- Replace the DME if the fault code is currently present or has been logged more than three times	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	none	Possible apparent symptoms None	Breakdown notice - none	A terminal status switch must be conducted before the fault can be cleared
VEID17.2 - BND200	S23AF	1019	Ambient pressure sensor, plausibility: Pressure irregularities	The diagnostic function monitors variations in the barometric pressure reading for plausibility	P1247	Barometric Pressure Plausibility	Ambient Pressure	Plausibility	The fault is recognized when the value remains constant Potential problem scenario(s): - DME defective	This fault is logged in the control module's fault memory immediately	Terminal 15	none	none	none	NO	none	Y	- DME defective	- Replace the DME if the fault code is currently present or has been logged more than three times	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	none	Possible apparent symptoms None	Breakdown notice - none	A terminal status switch must be conducted before the fault can be cleared
VEID17.2 - BND200	S23AC	1006	Throttle valve angle, intake manifold pressure, correlation: Limit value exceeded	The diagnostic function monitors the throttle valve aperture and the current intake manifold pressure reading to determine whether they are mutually plausible	P121F	Manifold Absolute Pressure to Throttle Angle - Top High (Bank 1)	Manifold Absolute Pressure	Correlation	The fault is recognized when the relationship between the indicated intake manifold pressure and the mean airflow calculated based on throttle valve angle is not correct Potential problem scenario(s): - Measured value for intake manifold pressure (P1245) too high - Vacuum leak within induction turbocharger - Increased throttle valve angle - Throttle valve sensor defective	This fault is logged in the control module's fault memory immediately	none	none	30°C + valve at temperature + 120°C 1500 rpm + engine speed + 120°C + constant	NO	none	Y	- Measured value for intake manifold pressure (calculated too high) - Vacuum leak within induction turbocharger - Increased throttle valve angle - Throttle valve sensor defective	- Check intake system and check for leakage - Check throttle valve combination, carbon deposits, ring - Check plug and wiring harness between intake manifold pressure sensor and DME - Check plug, wiring harness at electric throttle valve actuator - Replace pressure sensor - Replace throttle valve	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	none	Possible apparent symptoms None	Breakdown notice - none	None	
VEID17.2 - BND200	S23BA	1001	Throttle valve angle, intake manifold pressure, correlation: Limit value not exceeded	The diagnostic function monitors the throttle valve aperture and the current intake manifold pressure reading to determine whether they are mutually plausible	P121E	Manifold Absolute Pressure to Throttle Angle - Top Low (Bank 1)	Manifold Absolute Pressure	Correlation	The fault is recognized when the relationship between the indicated intake manifold pressure and the mean airflow calculated based on throttle valve angle is not correct Potential problem scenario(s): - Measured value for intake manifold pressure (P1245) is too low - Defective plug or wiring harness - Vacuum leak within induction turbocharger - Increased throttle valve angle	This fault is logged in the control module's fault memory immediately	none	none	none	NO	none	Y	- Measured value for intake manifold pressure (calculated too low) - Defective plug or wiring harness - Vacuum leak within induction turbocharger - Increased throttle valve angle - Pressure sensor defective	- Check intake system and check for leakage - Check throttle valve combination, carbon deposits, ring - Check plug and wiring harness between intake manifold pressure sensor and DME - Check plug, wiring harness at electric throttle valve actuator - Replace pressure sensor - Replace throttle valve	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	none	Possible apparent symptoms None	Breakdown notice - none	None	
VEID17.2 - BND200	S23BA	1004	Throttle valve, throttle valve potentiometer 1, electrical short circuit to GND or open circuit	The diagnostic function checks the signal from throttle valve actuator 1 for electrical faults	P1213	Throttle/Position Sensor/Switch X Circuit High	Throttle Position Sensor	1	The signal from throttle valve sensor 1 goes above the fault threshold of 0.1 V Potential problem scenario(s): - Defect in wiring harness between throttle valve actuator motor and DME - Throttle valve sensor defective - AD connector plug in DME	This fault is logged in the control module's fault memory immediately	Terminal 15	none	none	none	NO	none	Y	- Defect in wiring harness between throttle valve actuator motor and DME - Throttle valve sensor defective - AD connector plug in DME defective	- Check wiring harness between DME and throttle valve - Replace throttle valve - Replace DME	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	none	Possible apparent symptoms Reduced power	Breakdown notice - none	- It is possible to continue driving the vehicle, but passing requirements should not be attempted until the induction is engine adjust
VEID17.2 - BND200	S23BA	1005	Throttle valve, throttle valve potentiometer 1, electrical short circuit to earth	The diagnostic function checks the signal from throttle valve actuator 1 for electrical faults	P1212	Throttle/Position Sensor/Switch X Circuit Low	Throttle Position Sensor	1	The signal from throttle valve sensor 1 goes below the fault threshold of 0.1 V Potential problem scenario(s): - Defect in wiring harness between throttle valve actuator motor and DME - Throttle valve sensor defective - AD connector plug in DME	This fault is logged in the control module's fault memory immediately	Terminal 15	none	none	none	NO	none	Y	- Defect in wiring harness between throttle valve actuator motor and DME - Throttle valve sensor defective - AD connector plug in DME defective	- Check wiring harness between DME and throttle valve - Replace throttle valve - Replace DME	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	none	Possible apparent symptoms Reduced power	Breakdown notice - none	- It is possible to continue driving the vehicle, but passing requirements should not be attempted until the induction is engine adjust
VEID17.2 - BND200	S23BA	1009	Throttle valve, throttle potentiometer 2, electrical short circuit to GND	The diagnostic function checks the voltage of throttle valve sensor 2 for electrical faults	P1213	Throttle/Position Sensor/Switch X Circuit High	Throttle Position Sensor	2	The voltage of the throttle valve sensor 2 goes above the fault threshold of 0.1 V Potential problem scenario(s): - Defect in wiring harness between throttle valve actuator motor and DME - Throttle valve sensor defective - AD connector plug in DME	This fault is logged in the control module's fault memory immediately	Terminal 15	none	none	none	NO	none	Y	- Defect in wiring harness between throttle valve actuator motor and DME - Throttle valve sensor defective - AD connector plug in DME defective	- Check wiring harness between DME and throttle valve - Replace throttle valve - Replace DME	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	none	Possible apparent symptoms Reduced power	Breakdown notice - none	- It is possible to continue driving the vehicle, but passing requirements should not be attempted until the induction is engine adjust

MEVD12.2 BN2000	Su205A	11010	VANOS intake control fault, camshaft stuck	The diagnostic function monitors the camshaft timing adjustment	P1203	V Camshaft Shock	Camshaft	Intake Shock	The actual angle fails to conform to the specified angle while the engine is running	Potential problem scenario(s) - Contaminated of passage at VANOS selected valve - Oil pressure too low - Defect in wiring harness to VANOS selected valve - VANOS selected valve seized	The diagnostic fault code is triggered when the fault remains present for longer than 1 min.	none	Engine warmed to normal temperature, more than 80°C	None	Yes	NO	NO	Y	Y	Contaminated of passage at VANOS selected valve - Oil pressure too low - Defect in wiring harness to VANOS selected valve - VANOS selected valve seized - VANOS selected valve defective	- Check oil level, change engine oil and filter as indicated - If fault related to the camshaft position sensor have been triggered, repair these first - Check wiring harness between VANOS selected valve and VANOS - Perform system test - Check camshaft and VANOS unit for freedom of movement and mechanical damage - Clean VANOS selected valve, replace as required - Clean VANOS selected valve, replace as required	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	Fail leads to AT/CT/lines PC Test LES.4 Throttle pressure control, description: Boost pressure generation disabled? FC (Doc:Func) LA 1100800 (D/2049E, FC (Doc:Func) LA 110021 (D/2026)	Possible apparent symptoms - Engine runs poorly	Breakdown notice The engine reverts to an emergency limp home program, continue vehicle operation as possible, because power is reduced the driver should refrain from passing maneuvers	None
MEVD12.2 BN2000	Su205B	11011	VANOS intake control fault, position not reached	The diagnostic function monitors the camshaft timing adjustment	P1212	V Camshaft Position - Timing Clear Reached (Bank 1)	Camshaft Position Timing	Idle	The actual angle deviates from the specified angle while the engine is running	Potential problem scenario(s) - Contaminated of passage at VANOS selected valve - Oil pressure too low - Defective wiring plug terminals on VANOS selected valve - VANOS selected valve seized	The diagnostic fault code is triggered when the fault remains present for longer than 1 min.	none	Engine warmed to normal temperature, more than 80°C	None	Yes	NO	NO	Y	Y	Contaminated of passage at VANOS selected valve - Oil pressure too low - Defective wiring plug terminals on VANOS selected valve - VANOS selected valve seized - VANOS selected valve defective	- Check oil level, change engine oil and filter as indicated - If fault related to the camshaft position sensor have been triggered, repair these first - Check wiring harness between VANOS selected valve and DME - Perform system test - Check camshaft and VANOS unit for freedom of movement and mechanical damage - Clean VANOS selected valve, replace as required	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	Fail leads to AT/CT/lines PC Test LES.4 Throttle pressure control, description: Boost pressure generation disabled? FC (Doc:Func) LA 1100800 (D/2049E, FC (Doc:Func) LA 110021 (D/2026)	Possible apparent symptoms - Engine runs poorly	Breakdown notice The engine reverts to an emergency limp home program, continue vehicle operation as possible, because power is reduced the driver should refrain from passing maneuvers	None
MEVD12.2 BN2000	Su206	11016	VANOS exhaust control fault, camshaft stuck	The diagnostic function monitors the camshaft timing adjustment	P1203	V Camshaft Shock	Camshaft	Exhaust Shock	The actual angle fails to conform to the specified angle while the engine is running	Potential problem scenario(s) - Contaminated of passage at VANOS selected valve - Oil pressure too low - Defect in wiring harness to VANOS selected valve - VANOS selected valve seized	The diagnostic fault code is triggered when the fault remains present for longer than 1 min.	none	Engine warmed to normal temperature, more than 80°C	None	Yes	NO	NO	Y	Y	Contaminated of passage at VANOS selected valve - Oil pressure too low - Defect in wiring harness to VANOS selected valve - VANOS selected valve seized - VANOS selected valve defective	- Check oil level, change engine oil and filter as indicated - If fault related to the camshaft position sensor have been triggered, repair these first - Check wiring harness between VANOS selected valve and VANOS - Perform system test - Check camshaft and VANOS unit for freedom of movement and mechanical damage - Clean VANOS selected valve, replace as required	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	Fail leads to AT/CT/lines PC Test LES.4 Throttle pressure control, description: Boost pressure generation disabled? FC (Doc:Func) LA 1100800 (D/2049E, FC (Doc:Func) LA 110021 (D/2026)	Possible apparent symptoms - Engine runs poorly	Breakdown notice The engine reverts to an emergency limp home program, continue vehicle operation as possible, because power is reduced the driver should refrain from passing maneuvers	None
MEVD12.2 BN2000	Su206	11017	VANOS exhaust control fault, position not reached	The diagnostic function monitors the camshaft timing adjustment	P1212	V Camshaft Position - Timing Clear Reached (Bank 1)	Camshaft Position Timing	Exhaust	The actual angle deviates from the specified angle while the engine is running	Potential problem scenario(s) - Contaminated of passage at VANOS selected valve - Oil pressure too low - Defective wiring plug terminals on VANOS selected valve - VANOS selected valve seized	The diagnostic fault code is triggered when the fault remains present for longer than 1 min.	none	Engine warmed to normal temperature, more than 80°C	None	Yes	NO	NO	Y	Y	Contaminated of passage at VANOS selected valve - Oil pressure too low - Defective wiring plug terminals on VANOS selected valve - VANOS selected valve seized - VANOS selected valve defective	- Check oil level, change engine oil and filter as indicated - If fault related to the camshaft position sensor have been triggered, repair these first - Check wiring harness between VANOS selected valve and DME - Perform system test - Check camshaft and VANOS unit for freedom of movement and mechanical damage - Clean VANOS selected valve, replace as required	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	Fail leads to AT/CT/lines PC Test LES.4 Throttle pressure control, description: Boost pressure generation disabled? FC (Doc:Func) LA 1100800 (D/2049E, FC (Doc:Func) LA 110021 (D/2026)	Possible apparent symptoms - Engine runs poorly	Breakdown notice The engine reverts to an emergency limp home program, continue vehicle operation as possible, because power is reduced the driver should refrain from passing maneuvers	None
MEVD12.2 BN2000	Su208	11079	Exhaust VANOS selected valve, activation short circuit to +	The diagnostic function monitors the wire to the VANOS selected valve	P2001	V Camshaft Position Actuator Control High (Bank 1)	Camshaft Position Actuator	Exhaust Electrical	The actual circuit's diagnostic function <th>- Defect in wiring harness between DME and VANOS selected valve - VANOS selected valve defective - VANOS selected valve seized</th> <th>This fault is triggered in the control module's fault memory immediately</th> <th>none</th> <th>None</th> <th>None</th> <th>None</th> <th>NO</th> <th>NO</th> <th>Y</th> <th>Y</th> <th>- Defect in wiring harness between DME and VANOS selected valve - VANOS selected valve defective - VANOS selected valve seized</th> <th>- Check wiring harness between DME and VANOS selected valve - Replace VANOS selected valve - Replace DME</th> <th>- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on</th> <th>Fail leads to AT/CT/lines PC Test LES.4 Throttle pressure control, description: Boost pressure generation disabled? FC (Doc:Func) LA 1100800 (D/2049E, FC (Doc:Func) LA 110021 (D/2026)</th> <th>Possible apparent symptoms - CC message, performance reduction, turbo</th> <th>Breakdown notice None</th> <th>None</th>	- Defect in wiring harness between DME and VANOS selected valve - VANOS selected valve defective - VANOS selected valve seized	This fault is triggered in the control module's fault memory immediately	none	None	None	None	NO	NO	Y	Y	- Defect in wiring harness between DME and VANOS selected valve - VANOS selected valve defective - VANOS selected valve seized	- Check wiring harness between DME and VANOS selected valve - Replace VANOS selected valve - Replace DME	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	Fail leads to AT/CT/lines PC Test LES.4 Throttle pressure control, description: Boost pressure generation disabled? FC (Doc:Func) LA 1100800 (D/2049E, FC (Doc:Func) LA 110021 (D/2026)	Possible apparent symptoms - CC message, performance reduction, turbo	Breakdown notice None	None
MEVD12.2 BN2000	Su208	11079	Exhaust VANOS selected valve, activation short circuit to earth	The diagnostic function monitors the wire to the VANOS selected valve	P2002	V Camshaft Position Actuator Control Low (Bank 1)	Camshaft Position Actuator	Exhaust Electrical	The actual circuit's diagnostic function <th>- Defect in wiring harness between DME and VANOS selected valve - VANOS selected valve defective - VANOS selected valve seized</th> <th>This fault is triggered in the control module's fault memory immediately</th> <th>none</th> <th>None</th> <th>None</th> <th>None</th> <th>NO</th> <th>NO</th> <th>Y</th> <th>Y</th> <th>- Defect in wiring harness between DME and VANOS selected valve - VANOS selected valve defective - VANOS selected valve seized</th> <th>- Check wiring harness between DME and VANOS selected valve - Replace VANOS selected valve - Replace DME</th> <th>- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on</th> <th>Fail leads to AT/CT/lines PC Test LES.4 Throttle pressure control, description: Boost pressure generation disabled? FC (Doc:Func) LA 1100800 (D/2049E, FC (Doc:Func) LA 110021 (D/2026)</th> <th>Possible apparent symptoms - CC message, performance reduction, turbo</th> <th>Breakdown notice None</th> <th>None</th>	- Defect in wiring harness between DME and VANOS selected valve - VANOS selected valve defective - VANOS selected valve seized	This fault is triggered in the control module's fault memory immediately	none	None	None	None	NO	NO	Y	Y	- Defect in wiring harness between DME and VANOS selected valve - VANOS selected valve defective - VANOS selected valve seized	- Check wiring harness between DME and VANOS selected valve - Replace VANOS selected valve - Replace DME	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	Fail leads to AT/CT/lines PC Test LES.4 Throttle pressure control, description: Boost pressure generation disabled? FC (Doc:Func) LA 1100800 (D/2049E, FC (Doc:Func) LA 110021 (D/2026)	Possible apparent symptoms - CC message, performance reduction, turbo	Breakdown notice None	None
MEVD12.2 BN2000	Su20F	11079	Intake camshaft sensor, signal implausible	The diagnostic function monitors the intake camshaft position sensor	P0341	Camshaft Position Sensor V Circuit Range/Performance, Bank 1 (Single Sensor)	Camshaft Position Sensor	Intake Plausibility	The actual reference position does not align with the specified position	- Loose center bolt - Camshaft position sensor rotor ring out of adjustment - Timing chain has jumped line - Defective wiring harness	If the crankshaft reference position has been present	none	None	None	NO	NO	NO	Y	Y	- Loose center bolt - Camshaft position sensor rotor ring out of adjustment - Timing chain has jumped line - Defective wiring harness	- When intake and exhaust camshafts display synchronous angular offset errors relative to camshaft, check center bolt - Check camshaft position sensor rotor ring installation - Check timing chain - Check valve timing	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	Fail leads to AT/CT/lines PC Test LES.4 Throttle pressure control, description: Boost pressure generation disabled? FC (Doc:Func) LA 1100800 (D/2049E, FC (Doc:Func) LA 110021 (D/2026)	Possible apparent symptoms - Non-synchronous engine operation	Breakdown notice The engine reverts to an emergency limp home program, continue vehicle operation as possible, because power is reduced the driver should refrain from passing maneuvers	None
MEVD12.2 BN2000	Su20A	11080	Intake camshaft, angle offset with respect to camshaft outside tolerance	The diagnostic function monitors the camshaft angle between camshaft and camshaft position sensor	P1208	Camshaft Position Sensor V Faulty Phase (Bank 1)	Camshaft Position Sensor	Intake Phase	The actual reference position does not align with the specified position	- Loose center bolt - Camshaft position sensor rotor ring out of adjustment - Timing chain has jumped line - Defective wiring harness	If the crankshaft reference position has been present	none	None	None	NO	NO	NO	Y	Y	- Loose center bolt - Camshaft position sensor rotor ring out of adjustment - Timing chain has jumped line - Defective wiring harness	- When intake and exhaust camshafts display asynchronous angular offset errors relative to camshaft, check center bolt - Check camshaft position sensor rotor ring installation - Check timing chain - Check valve timing	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	Fail leads to AT/CT/lines PC Test LES.4 Throttle pressure control, description: Boost pressure generation disabled? FC (Doc:Func) LA 1100800 (D/2049E, FC (Doc:Func) LA 110021 (D/2026)	Possible apparent symptoms - ILL, spark on	Breakdown notice The engine reverts to an emergency limp home program, continue vehicle operation as possible, because power is reduced the driver should refrain from passing maneuvers	None
MEVD12.2 BN2000	Su20A	11081	Exhaust camshaft sensor, signal implausible	The diagnostic function monitors the exhaust camshaft position sensor	P0300	Camshaft Position Sensor V Circuit Range/Performance, Bank 1	Camshaft Position Sensor	Exhaust Plausibility	The actual reference position does not align with the specified position	- Loose center bolt - Camshaft position sensor rotor ring out of adjustment - Timing chain has jumped line - Defective wiring harness	If the crankshaft reference position has been present	none	None	None	NO	NO	NO	Y	Y	- Loose center bolt - Camshaft position sensor rotor ring out of adjustment - Timing chain has jumped line - Defective wiring harness	- When intake and exhaust camshafts display asynchronous angular offset errors relative to camshaft, check center bolt - Check camshaft position sensor rotor ring installation - Check timing chain - Check valve timing	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	Fail leads to AT/CT/lines PC Test LES.4 Throttle pressure control, description: Boost pressure generation disabled? FC (Doc:Func) LA 1100800 (D/2049E, FC (Doc:Func) LA 110021 (D/2026)	Possible apparent symptoms - Non-synchronous engine operation	Breakdown notice The engine reverts to an emergency limp home program, continue vehicle operation as possible, because power is reduced the driver should refrain from passing maneuvers	None
MEVD12.2 BN2000	Su20A	11082	Exhaust camshaft, angle offset with respect to camshaft outside tolerance	The diagnostic function monitors the offset angle between camshaft and camshaft position sensor	P1208	Camshaft Position Sensor V Faulty Phase (Bank 1)	Camshaft Position Sensor	Exhaust Phase	The actual reference position does not align with the specified position	- Loose center bolt - Camshaft position sensor rotor ring out of adjustment - Timing chain has jumped line - Defective wiring harness	If the crankshaft reference position has been present	none	None	None	NO	NO	NO	Y	Y	- Loose center bolt - Camshaft position sensor rotor ring out of adjustment - Timing chain has jumped line - Defective wiring harness	- When intake and exhaust camshafts display asynchronous angular offset errors relative to camshaft, check center bolt - Check camshaft position sensor rotor ring installation - Check timing chain - Check valve timing	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	Fail leads to AT/CT/lines PC Test LES.4 Throttle pressure control, description: Boost pressure generation disabled? FC (Doc:Func) LA 1100800 (D/2049E, FC (Doc:Func) LA 110021 (D/2026)	Possible apparent symptoms - Non-synchronous engine operation	Breakdown notice The engine reverts to an emergency limp home program, continue vehicle operation as possible, because power is reduced the driver should refrain from passing maneuvers	None
MEVD12.2 BN2000	Su20B	11086	VANOS intake intake camshaft not in locking position at start up	The diagnostic function monitors camshaft position locking	P1205	B Camshaft Starting Position not Reached (Bank 1)	Camshaft	None	The camshaft is not locked during starting <th>- Engine oil dirty, old or not to specification - VANOS adjustment unit dirty - VANOS adjustment unit defective</th> <th>The fault is triggered immediately when it occurs during an engine start</th> <th>none</th> <th>None</th> <th>None</th> <th>NO</th> <th>NO</th> <th>Y</th> <th>Y</th> <th>- Engine oil dirty, old or not to specification - Perform system test on VANOS selected valve - Replace VANOS adjustment unit</th> <th>- Check engine oil, replace engine oil and filter as required - Perform system test on VANOS selected valve</th> <th>- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message, none</th> <th>none</th> <th>Breakdown notice None</th> <th>None</th>	- Engine oil dirty, old or not to specification - VANOS adjustment unit dirty - VANOS adjustment unit defective	The fault is triggered immediately when it occurs during an engine start	none	None	None	NO	NO	Y	Y	- Engine oil dirty, old or not to specification - Perform system test on VANOS selected valve - Replace VANOS adjustment unit	- Check engine oil, replace engine oil and filter as required - Perform system test on VANOS selected valve	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message, none	none	Breakdown notice None	None		
MEVD12.2 BN2000	Su20B	11087	VANOS intake intake camshaft not in locking position at start up	The diagnostic function monitors camshaft position locking	P1203	A Camshaft Starting Position not Reached (Bank 1)	Camshaft	None	The camshaft is not locked during starting <th>- Engine oil dirty, old or not to specification - VANOS adjustment unit dirty - VANOS adjustment unit defective</th> <th>The fault is triggered immediately when it occurs during an engine start</th> <th>none</th> <th>None</th> <th>None</th> <th>NO</th> <th>NO</th> <th>Y</th> <th>Y</th> <th>- Engine oil dirty, old or not to specification - Perform system test on VANOS selected valve - Replace VANOS adjustment unit</th> <th>- Check engine oil, replace engine oil and filter as required - Perform system test on VANOS selected valve</th> <th>- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message, none</th> <th>none</th> <th>Breakdown notice None</th> <th>None</th>	- Engine oil dirty, old or not to specification - VANOS adjustment unit dirty - VANOS adjustment unit defective	The fault is triggered immediately when it occurs during an engine start	none	None	None	NO	NO	Y	Y	- Engine oil dirty, old or not to specification - Perform system test on VANOS selected valve - Replace VANOS adjustment unit	- Check engine oil, replace engine oil and filter as required - Perform system test on VANOS selected valve	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message, none	none	Breakdown notice None	None		
MEVD12.2 BN2000	Su20A	11100	Valetronics relay, activation, short circuit to +	The diagnostic function monitors electrical activation of the Valetronics relay for a short circuit to positive	P1208	VVT Relay Control High	Valetronics (VVT)	Relay	The fault is recognized when a short circuit to ground is detected when activation voltage is transmitted to the Valetronics relay	- Defective wiring harness - Valetronics relay defective - Defective DME	This fault is triggered in the control module's fault memory immediately	Terminal 15	None	None	None	NO	NO	Y	Y	- Defective wiring harness - Valetronics relay defective - Defective DME	- Inspect wiring harness between DME and Valetronics relay - Replace Valetronics relay - Replace DME	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	none	Possible apparent symptoms - Non-synchronous engine operation	Breakdown notice None	None
MEVD12.2 BN2000	Su20B	11101	Valetronics relay, activation, short circuit to earth	The diagnostic function monitors electrical activation of the Valetronics relay for a short circuit to ground	P1207	VVT Relay Control Low	Valetronics (VVT)	Relay	The fault is recognized when a short circuit to ground is detected when activation voltage is transmitted to the Valetronics relay	- Defective wiring harness - Valetronics relay defective - Defective DME	This fault is triggered in the control module's fault memory immediately	Terminal 15	None	None	None	NO	NO	Y	Y	- Defective wiring harness - Valetronics relay defective - Defective DME	- Inspect wiring harness between DME and Valetronics relay - Replace Valetronics relay - Replace DME	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	none	Possible apparent symptoms - Non-synchronous engine operation	Breakdown notice None	None
MEVD12.2 BN2000	Su20B	11102	Valetronics relay, activation, line disconnection	The diagnostic function monitors electrical activation of the Valetronics relay for open circuit	P1208	VVT Relay Control High	Valetronics (VVT)	Relay	The fault is recognized when a short circuit to ground is detected when activation voltage is transmitted to the Valetronics relay	- Defective wiring harness - Valetronics relay defective - Defective DME	This fault is triggered in the control module's fault memory immediately	Terminal 15	None	None	None	NO	NO	Y	Y	- Defective wiring harness - Valetronics relay defective - Defective DME	- Inspect wiring harness between DME and Valetronics relay - Replace Valetronics relay - Replace DME	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message, none	none	Possible apparent symptoms - Non-synchronous engine operation	Breakdown notice None	None
MEVD12.2 BN2000	Su20B	11106	Valetronics component protection, output stage system switch-off	The diagnostic function monitors the temperature of the short circuit	P120F	VVT Overload Protection Output Stage System Disruption	Valetronics (VVT)	Overload Protection	The calculated short circuit temperature rises above 130°C	- Valetronics system component excessive energy input - Solution and high resistance in the Valetronics system - Other conditions	none	Terminal 15	None	None	None	NO	NO	Y	Y	- Check electrical system voltage - If other diagnostic fault codes related to Valetronics are triggered, work through these first - Check Valetronics mechanism for freedom of movement, wear and adjust left external valve gear base operation (stop home maintenance/overhaul) - Replace components with mechanical wear	- Check electrical system voltage - If other diagnostic fault codes related to Valetronics are triggered, work through these first - Check Valetronics mechanism for freedom of movement, wear and adjust left external valve gear base operation (stop home maintenance/overhaul) - Replace components with mechanical wear	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	none	Possible apparent symptoms - Range from no effect to power reduction/abandonment	Breakdown notice VVT driver circuit component protection	None
MEVD12.2 BN2000	Su20B	11107	Valetronics component protection, activation system switch-off	The diagnostic function monitors the temperature of the Valetronics actuator motor when above 200°C (200°C temperature in the windings of the Valetronics motor)	P120F	VVT Overload Protection Control Motor System Disruption	Valetronics (VVT)	Overload Protection	The calculated short circuit temperature rises above 130°C	- Valetronics system component excessive energy input - Solution and high resistance in the Valetronics system - Other conditions	none	Terminal 15	None	None	None	NO	NO	Y	Y	- Check electrical system voltage - If other diagnostic fault codes related to Valetronics are triggered, work through these first - Check Valetronics mechanism for freedom of movement, wear and adjust left external valve gear base operation (stop home maintenance/overhaul) - Replace components with mechanical wear	- Check electrical system voltage - If other diagnostic fault codes related to Valetronics are triggered, work through these first - Check Valetronics mechanism for freedom of movement, wear and adjust left external valve gear base operation (stop home maintenance/overhaul) - Replace components with mechanical wear	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	none	Possible apparent symptoms - Range from no effect to power reduction/abandonment	Breakdown notice VVT driver circuit component protection	None
MEVD12.2 BN2000	Su20B	11108	Valetronics, excessive shaft oscillation, lower stop reached	Open	-	-	-	Other conditions	-	-	-	-	None	None	NO	NO	Y	Y	-	-	-	-	none for 10-20-400	Possible apparent symptoms - Customer perception in noise at this position	Breakdown notice None	None
MEVD12.2 BN2000	Su20F	11111	Valetronics sensor, activation, short circuit to +	The diagnostic function monitors the Valetronics actuator motor's trip phase for a short circuit to positive	P1207	VVT Control Circuit High (Bank 1)	Valetronics (VVT)	Control Motor	The fault is recognized when a fault is detected. The fault is triggered when the measured negative voltage is greater than 2 V (2.3 V and the voltage tolerance may increase 10°C)	- Defective wiring harness - Defective Valetronics actuator motor relay	This fault is triggered in the control module's fault memory immediately	Terminal 15	None	None	None	NO	NO	Y	Y	- Defective wiring harness - Valetronics actuator defective	- Check wiring harness between Valetronics actuator motor and DME - Replace Valetronics actuator motor	- ECE emissions warning lamp on - ECE electronic engine power reduction on - CC message on - US emissions warning lamp on - US electronic engine power reduction on - CC message on	none	Possible apparent symptoms - If the malfunction occurs while the VVT system is at maximum intake volume (full load, vehicle parked), only limited or no effects will be apparent in the customer. (disturbance process may be felt after CO2 loading required) - Otherwise breakdown notice, as power is no longer transmitted to the VVT system, which this class.	Breakdown notice No continued driving possible	None

MEVD11.2	IN2000	32F76	1202	Combustion mixing, cylinder 6. Spark duration too short	The diagnostic function monitors the duration of the combustion stroke and compares them with the remaining cylinders by assessing the pyro-sensors (ignition timing)	P1308	Cylinder 6 Misfire Detected	Misfire	Cyl 6	The combustion stroke in a particular cylinder is shorter than the combustion stroke in the other cylinders	Potential problem scenario(s): - Defect in mixture formation - Defect in ignition system - Mechanical defect - Defective DME	Diagnostic fault code is triggered when a specific sensor of combustion mix events, with their respective mixture or ignition, are recognized during the first 1000 crankshaft revolutions following the start	None	None	NO	None	Y	- Defect in mixture formation - Defect in ignition system - Mechanical defect - Defective DME	- Decrease this to a secondary fault, start by repairing the primary fault	None	Possible apparent symptoms: Combustion mix may be reduced	Breakdown notice: None	None		
MEVD11.2	IN2000	32F76	1203			P1309	Random/Multiple Cylinder Misfire Detected	Misfire	Multiple																
MEVD11.2	IN2000	32F77	1201			P1301	Cylinder 1 Misfire Detected	Misfire	Cyl 1																
MEVD11.2	IN2000	32F78	1202			P1302	Cylinder 2 Misfire Detected	Misfire	Cyl 2																
MEVD11.2	IN2000	32F79	1203			P1303	Cylinder 3 Misfire Detected	Misfire	Cyl 3																
MEVD11.2	IN2000	32F80	1204			P1304	Cylinder 4 Misfire Detected	Misfire	Cyl 4																
MEVD11.2	IN2000	32F81	1205			P1305	Cylinder 5 Misfire Detected	Misfire	Cyl 5																
MEVD11.2	IN2000	32F84	1210	Ignition circuit, supply voltage. Bank 0 engine failure	The diagnostic function simultaneously monitors the spark duration in all cylinders	P1344				The fault is recognized when the spark duration is too short in all cylinders at once	Potential problem scenario(s): - Defect in power voltage supply	If the fault 7 then 8 is triggered	Terminal 10	None	None	NO	None	Y	- Defect in power voltage supply	- Check power supply of ignition coils	Ignition failure encompassing of cylinders, fault described after of combustion duration > 1.0s	Possible apparent symptoms: Motor does not run	Breakdown notice: None	None	
MEVD11.2	IN2000	32F44	1211	Irregular operation, single cylinder firing. Torque combustion low	The diagnostic function monitors the 7	P1343				The fault is recognized when a high number of misfire events is detected during engine operation in the upper end of the load range	Potential problem scenario(s): - Misfire, terminal status switch during vehicle operation	If the fault 7 then 8 is triggered	None	Other conditions: - Engine in upper load range	None	None	NO	None	Y	- ECE emission warning lamp on - ECE electronic engine power reduction of -CC message - misfire - US emissions warning lamp on - US electronic engine power reduction of -CC message - misfire	Customer attention in case of the failure	Breakdown notice: None	None		
MEVD11.2	IN2000	32F76	1210	Super knocking, cylinder 1. Injection switch-off	The diagnostic function responds to extreme combustion knock by deactivating the injection at the 1st cylinder	P1340	Knock Control Fuel Cut-Off due to Super Knocking Cylinder 1			The diagnostic fault code is triggered when the fuel sensor present for longer than 1.0s	Potential problem scenario(s): - Misfire, terminal status switch during vehicle operation	If the diagnostic fault code is triggered when the fuel sensor present for longer than 1.0s	None	Other conditions: - Engine in upper load range	Engine warmed to normal temperature, more than 80 °C	None	NO	None	Y	- Misfire, terminal status switch during vehicle operation - Temporary contamination in combustion chamber or intake passages	- If the diagnostic fault code has been triggered once, clear the ECU fault memory - If the fault has been triggered multiple times, check the spark plug, injector and ignition coil on the cylinder	None	Possible apparent symptoms: Engine runs poorly with power loss	Breakdown notice: None	None
MEVD11.2	IN2000	32F77	1211	Super knocking, cylinder 2. Injection switch-off	The diagnostic function responds to extreme combustion knock by deactivating the injection at the 2nd cylinder	P1341	Knock Control Fuel Cut-Off due to Super Knocking Cylinder 2			The diagnostic fault code is triggered when the fuel sensor present for longer than 1.0s	Potential problem scenario(s): - Misfire, terminal status switch during vehicle operation	If the diagnostic fault code is triggered when the fuel sensor present for longer than 1.0s	None	Other conditions: - Engine in upper load range	Engine warmed to normal temperature, more than 80 °C	None	NO	None	Y	- Misfire, terminal status switch during vehicle operation - Temporary contamination in combustion chamber or intake passages	- If the diagnostic fault code has been triggered once, clear the ECU fault memory - If the fault has been triggered multiple times, check the spark plug, injector and ignition coil at cylinder 2	None	Possible apparent symptoms: Engine runs poorly with power loss	Breakdown notice: None	None
MEVD11.2	IN2000	32F78	1212	Super knocking, cylinder 3. Injection switch-off	The diagnostic function responds to extreme combustion knock by deactivating the injection at the 3rd cylinder	P1342	Knock Control Fuel Cut-Off due to Super Knocking Cylinder 3			The diagnostic fault code is triggered when the fuel sensor present for longer than 1.0s	Potential problem scenario(s): - Misfire, terminal status switch during vehicle operation	If the diagnostic fault code is triggered when the fuel sensor present for longer than 1.0s	None	Other conditions: - Engine in upper load range	Engine warmed to normal temperature, more than 80 °C	None	NO	None	Y	- Misfire, terminal status switch during vehicle operation - Temporary contamination in combustion chamber or intake passages	- If the diagnostic fault code has been triggered once, clear the ECU fault memory - If the fault has been triggered multiple times, check the spark plug, injector and ignition coil at cylinder 3	None	Possible apparent symptoms: Engine runs poorly with power loss	Breakdown notice: None	None
MEVD11.2	IN2000	32F79	1213	Super knocking, cylinder 4. Injection switch-off	The diagnostic function responds to extreme combustion knock by deactivating the injection at the 4th cylinder	P1343	Knock Control Fuel Cut-Off due to Super Knocking Cylinder 4			The diagnostic fault code is triggered when the fuel sensor present for longer than 1.0s	Potential problem scenario(s): - Misfire, terminal status switch during vehicle operation	If the diagnostic fault code is triggered when the fuel sensor present for longer than 1.0s	None	Other conditions: - Engine in upper load range	Engine warmed to normal temperature, more than 80 °C	None	NO	None	Y	- Misfire, terminal status switch during vehicle operation - Temporary contamination in combustion chamber or intake passages	- If the diagnostic fault code has been triggered once, clear the ECU fault memory - If the fault has been triggered multiple times, check the spark plug, injector and ignition coil at cylinder 4	None	Possible apparent symptoms: Engine runs poorly with power loss	Breakdown notice: None	None
MEVD11.2	IN2000	32F7A	1214	Super knocking, cylinder 5. Injection switch-off	The diagnostic function responds to extreme combustion knock by deactivating the injection at the 5th cylinder	P1344	Knock Control Fuel Cut-Off due to Super Knocking Cylinder 5			The diagnostic fault code is triggered when the fuel sensor present for longer than 1.0s	Potential problem scenario(s): - Misfire, terminal status switch during vehicle operation	If the diagnostic fault code is triggered when the fuel sensor present for longer than 1.0s	None	Other conditions: - Engine in upper load range	Engine warmed to normal temperature, more than 80 °C	None	NO	None	Y	- Misfire, terminal status switch during vehicle operation - Temporary contamination in combustion chamber or intake passages	- If the diagnostic fault code has been triggered once, clear the ECU fault memory - If the fault has been triggered multiple times, check the spark plug, injector and ignition coil on the cylinder	None	Possible apparent symptoms: Engine runs poorly with power loss	Breakdown notice: None	None
MEVD11.2	IN2000	32F7B	1215	Super knocking, cylinder 6. Injection switch-off	The diagnostic function responds to extreme combustion knock by deactivating the injection at the 6th cylinder	P1345	Knock Control Fuel Cut-Off due to Super Knocking Cylinder 6			The diagnostic fault code is triggered when the fuel sensor present for longer than 1.0s	Potential problem scenario(s): - Misfire, terminal status switch during vehicle operation	If the diagnostic fault code is triggered when the fuel sensor present for longer than 1.0s	None	Other conditions: - Engine in upper load range	Engine warmed to normal temperature, more than 80 °C	None	NO	None	Y	- Misfire, terminal status switch during vehicle operation - Temporary contamination in combustion chamber or intake passages	- If the diagnostic fault code has been triggered once, clear the ECU fault memory - If the fault has been triggered multiple times, check the spark plug, injector and ignition coil on the cylinder	None	Possible apparent symptoms: Engine runs poorly with power loss	Breakdown notice: None	None
MEVD11.2	IN2000	32F7C	1216	Super knocking, knock sensor switch-off	The diagnostic function responds to extreme combustion knock by deactivating the injection	P1347	Knocking	Knock Control System	Super Knocking	The diagnostic fault code is triggered when the fuel sensor present for longer than 1.0s	Potential problem scenario(s): - Misfire, terminal status switch during vehicle operation	If the diagnostic fault code is triggered when the fuel sensor present for longer than 1.0s	None	Other conditions: - Engine in upper load range	Engine warmed to normal temperature, more than 80 °C	None	NO	None	Y	- Misfire, terminal status switch during vehicle operation - Temporary contamination in combustion chamber or intake passages	- If the diagnostic fault code has been triggered once, clear the ECU fault memory - If the fault has been triggered multiple times, check the spark plug, injector and ignition coil on the cylinder	None	Possible apparent symptoms: Engine runs poorly with power loss	Breakdown notice: None	None
MEVD11.2	IN2000	32F81	1261	Ignition timing adjustment in idle, cold start. Ignition timing too early	The diagnostic function monitors the ignition angle while the catalytic converter is being heated	P1308	Cold Start Ignition Timing Performance	Ignition Timing	Cold Start	The fault is recognized when the ignition angle adjustment is outside the tolerance range	Potential problem scenario(s): - Poor fuel quality	This fault is triggered when the fault remains present for longer than 1.0s	None	1 sec. after engine on	None	None	NO	None	Y	- Poor fuel quality	- Replace fuel	US only, fuel based on legislative requirement, probably self-repair error	Possible apparent symptoms: None	Breakdown notice: None	None
MEVD11.2	IN2000	32F84	1264	Ignition timing adjustment at partial load, cold start. Ignition timing too early	The diagnostic function monitors the ignition angle while the catalytic converter is being heated	P130A	Cold Start Ignition Timing Performance Off-Idle	Ignition Timing	Cold Start	The fault is recognized when the ignition angle adjustment is outside the tolerance range	Potential problem scenario(s): - Poor fuel quality	This fault is triggered when the fault remains present for longer than 1.0s	None	1 sec. after engine on	None	None	NO	None	Y	- Poor fuel quality	- Replace fuel	US only, fuel based on legislative requirement, probably self-repair error	Possible apparent symptoms: None	Breakdown notice: None	None
MEVD11.2	IN2000	32F8A	1275	Ignition voltage supply. Short circuit to B+	The diagnostic function monitors the power supply wire providing voltage to the individual coil packs from the electrical protection relay for ignition and injection, checking for open wires and shorts to ground					The diagnostic fault code is triggered when the control module's fault memory immediately	Potential problem scenario(s): - Fuse defective - Defect in wiring harness between overboard protection relay for ignition and injection - Defective DME	This fault is triggered when the control module's fault memory immediately	Terminal 10	None	None	NO	U	None	Y	- Wiring harness between DME and overboard protection relay for ignition and injection - Defect in electrical protection relay for ignition and injection - Defective DME	- Inspect wiring harness between overboard protection relay for ignition and injection, and DME - Replace overboard protection relay for ignition and injection - Replace DME	None	Possible apparent symptoms: None	Breakdown notice: None	None
MEVD11.2	IN2000	32F8B	1271	Ignition, voltage supply. Line disconnection at short circuit to earth	The diagnostic function monitors the power supply wire providing voltage to the individual coil packs from the electrical protection relay for ignition and injection, checking for open wires and shorts to ground					The diagnostic fault code is triggered when the control module's fault memory immediately	Potential problem scenario(s): - Fuse defective - Defect in wiring harness between overboard protection relay for ignition and injection, and DME - Defective DME	This fault is triggered when the control module's fault memory immediately	Terminal 10	None	None	NO	U	None	Y	- Wiring harness between DME and overboard protection relay for ignition and injection, and DME - Defect in electrical protection relay for ignition and injection - Defective DME	- Check fuse - Inspect wiring harness between overboard protection relay for ignition and injection, and DME - Replace overboard protection relay for ignition and injection - Replace DME	None	Possible apparent symptoms: Non-start	Breakdown notice: None	None
MEVD11.2	IN2000	32F8F	1200	Combustion mix, cylinder 1. Spark duration too short	The diagnostic function monitors the spark duration					The spark duration is below a value stored in the program map	Potential problem scenario(s): - Defective spark plug - Defect in wiring harness between ignition coil and DME - Defective ignition coil	This diagnostic fault code is triggered when the fuel counter value is above 300	None	None	None	NO	None	Y	- Defective spark plug - Check wiring harness between ignition coil and DME - Replace DME if the fuel counter remains logged continuously	- Check wiring harness between ignition coil and DME - Check ignition coil - Replace DME if the fuel counter remains logged continuously	None	Possible apparent symptoms: Ignition noise and hard starting (at cold)	Breakdown notice: Continued driving possible if only the one cylinder is affected. The ignition mis-detection should recognize the affected cylinder and deactivate the injector to protect the catalytic converter	None	None
MEVD11.2	IN2000	32F8F	1201	Combustion mix, cylinder 2. Spark duration too short	The diagnostic function monitors the spark duration					The spark duration is below a value stored in the program map	Potential problem scenario(s): - Defective spark plug - Defect in wiring harness between ignition coil and DME - Defective ignition coil	This diagnostic fault code is triggered when the fuel counter value is above 300	None	None	None	NO	None	Y	- Defective spark plug - Check wiring harness between ignition coil and DME - Replace DME if the fuel counter remains logged continuously	- Check wiring harness between ignition coil and DME - Check ignition coil - Replace DME if the fuel counter remains logged continuously	None	Possible apparent symptoms: Ignition noise and hard starting (at cold)	Breakdown notice: Continued driving possible if only the one cylinder is affected. The ignition mis-detection should recognize the affected cylinder and deactivate the injector to protect the catalytic converter	None	None
MEVD11.2	IN2000	32F8F	1202	Combustion mix, cylinder 3. Spark duration too short	The diagnostic function monitors the spark duration					The spark duration is below a value stored in the program map	Potential problem scenario(s): - Defective spark plug - Defect in wiring harness between ignition coil and DME - Defective ignition coil	This diagnostic fault code is triggered when the fuel counter value is above 300	None	None	None	NO	None	Y	- Defective spark plug - Check wiring harness between ignition coil and DME - Replace DME if the fuel counter remains logged continuously	- Check wiring harness between ignition coil and DME - Check ignition coil - Replace DME if the fuel counter remains logged continuously	None	Possible apparent symptoms: Ignition noise and hard starting (at cold)	Breakdown notice: Continued driving possible if only the one cylinder is affected. The ignition mis-detection should recognize the affected cylinder and deactivate the injector to protect the catalytic converter	None	None
MEVD11.2	IN2000	32F8F	1203	Combustion mix, cylinder 4. Spark duration too short	The diagnostic function monitors the spark duration					The spark duration is below a value stored in the program map	Potential problem scenario(s): - Defective spark plug - Defect in wiring harness between ignition coil and DME - Defective ignition coil	This diagnostic fault code is triggered when the fuel counter value is above 300	None	None	None	NO	None	Y	- Defective spark plug - Check wiring harness between ignition coil and DME - Replace DME if the fuel counter remains logged continuously	- Check wiring harness between ignition coil and DME - Check ignition coil - Replace DME if the fuel counter remains logged continuously	None	Possible apparent symptoms: Ignition noise and hard starting (at cold)	Breakdown notice: Continued driving possible if only the one cylinder is affected. The ignition mis-detection should recognize the affected cylinder and deactivate the injector to protect the catalytic converter	None	None

