REP-REP-RAE8451-5145180 Removing and installing/replacing instrument panel trim, bottom left

VIN: XXXXXXX Vehicle: X'/E84/OFF-ROAD VEHICLE/X1

28iX/N20/AUTO/USA/LL/2013/12

System **3.48.20.13322** Data **R3.48.20.13322**

Version: Version:

51 45 180

Removing and installing/replacing instrument panel trim, bottom left



Important!


Risk of damage!

When working on trim panel components, make sure that the sensitive surfaces are not scratched or damaged.




Necessary preliminary tasks:

- Remove lower section of steering column trim
- Remove left fresh-air grill
- Remove trim panel for pedal assembly



Release screws (1) from lower dashboard trim panel (2).

Release plug connection (1) on light switch (2) and disconnect. Remove lower instrument panel trim.





Replacement

- Modify light switch
- Modify retaining clips and sheet metal nuts and renew if necessary.