



VIN:	VW52850	Vehicle:	X'/E84/OFF-ROAD VEHICLE/X1 28i/N20/AUTO/USA/LL/2013/07
System Version:	3.47.30.13232	Data Version:	R3.47.30.13232

51 49 000

Removing and installing or replacing trim
for tailgate



Remove warning triangle (1).



- Release screw (2) from warning triangle holder (4).
- Remove warning triangle holder (4).
- Release remaining bolts (2).
- Use appropriate tool to unclip trim panel (see highlighted area) from tailgate (1).
- US version only
 - Feed out tailgate lock with emergency release (3).
- Remove panel for tailgate (1).

- Installation:*
- Replace faulty clips (1).
 - Insert trim of tailgate properly.
 - US version only
 - Properly feed through emergency release of tailgate lock.
- Replacement**
- Modify clips (1).

