

REP-REP-RAE8451-5145187    Remove and install trim of instrument panel (steering column shroud, lower part) lower left side

---

VIN:	XXXXXXX	Vehicle:	X'E84/OFF-ROAD VEHICLE/X1 28iX/N20/AUTO/USA/LL/2013/12
System Version:	3.48.20.13322	Data Version:	R3.48.20.13322

---

51 45 187


Remove and install trim of instrument panel (steering column shroud, lower part) lower left side



**Important!**

Risk of damage!

When working on trim panel components, make sure that the sensitive surfaces are not scratched or damaged.



Remove clamps (highlighted area) from steering column shroud (1).

Remove steering column shroud (1).

*Installation:*

Clamps and retaining tabs must not be damaged.

Cleanly press in steering column shroud (1).